


# 1990 X2 PARTS DIAGRAM

Cables

F3175A



# 1990 X2 PARTS LIST

## Cables

ITEM NAME	PART NUMBER	QUANTITY
BOLT,5X16 (Ref # 110)	110R0516	4
NUT-HEX,5MM (Ref # 311)	311R0500	1
NUT-HEX,6MM (Ref # 311A)	311R0600	2
W-PLAIN-S,10MM (Ref # 410)	410S1000	1
O RING,11MM (Ref # 670)	670B2011	4
PLATE (Ref # 13183)	13169-3713	1
ROD,STEERING,6X190 (Ref # 46102)	46102-3704	1
ROD,L=40 (Ref # 46102A)	46102-3706	1
ROD,5X125 (Ref # 46102B)	46102-3707	1
BOOT (Ref # 49006)	49006-3706	1
CABLE-THROTTLE (Ref # 54012)	54012-3715	1
CABLE-STARTER (Ref # 54017)	54017-3714	1
CABLE-STRG,UP&DOWN (Ref # 59406)	59406-3711	1
CABLE-STRG (Ref # 59406A)	59406-3712	1
NUT,5MM (Ref # 92015)	92015-3754	1
NUT,20MM (Ref # 92015A)	92015-526	4
WASHER (Ref # 92022)	92022-535	4
RING-SNAP (Ref # 92033)	92036-501	4