


1982 AR80-A1 PARTS DIAGRAM

SWING ARM

F2140-0028



1982 AR80-A1 PARTS LIST

SWING ARM

ITEM NAME	PART NUMBER	QUANTITY
ARM-COMP-SWING (Ref # 33001)	33001-1072	1
SHAFT-SWING ARM,10X21 (Ref # 33032)	33032-1018	1
ADJUSTER CHAIN (Ref # 33040)	33040-008	2
WASHER,6.5X16X2 (Ref # 92022)	92022-1565	2
COLLAR,12.7X17.3X132. (Ref # 92027)	92027-1309	1
BUSHING,L=25 (Ref # 92028)	92028-1359	2
NUT 6MM (Ref # 311)	311B0600	4
NUT,10MM (Ref # 314)	314B1000	1
WASHER PLAIN 10MM (Ref # 411)	411B1000	2
WASHER SPRING 10MM (Ref # 461)	461F1000	1