


1978 KZ200-A1 PARTS DIAGRAM

TURN SIGNALS



1978 KZ200-A1 PARTS LIST

TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
LAMP,TURN SIGNAL (Ref # 1)	23040-054	4
BRACKET,TURN SIGNAL.L (Ref # 2)	23051-053	2
DAMPER RUBBER (Ref # 3)	92075-128	2
NUT 10MM (Ref # 4)	315B1000	2
SCREW-PAN HEAD,4X20 (Ref # 5)	220E0420A	8
WASHER-PLAIN,4MM (Ref # 6)	23058-002	8
LENS,TURN SIGNAL LAMP (Ref # 7)	23048-1001	4
GASKET-SIG LAMP LENS (Ref # 8)	23050-003	4
BULB 12V 32CP (Ref # 9)	92069-055	4
BOLT-UPSET (Ref # 10)	112G0630	4
WASHER PLAIN 6MM (Ref # 11)	411B0600	8
WASHER SPRING 6MM (Ref # 12)	461F0600	4
NUT 6MM (Ref # 13)	311B0600	4
BKT TURN SIGNL LIGHT (Ref # 14)	23051-049	2
CAP,SIGNAL LIGHT STAY (Ref # 15)	92102-015	2
DAMPER RUBBER,SIGNAL (Ref # 16)	92075-241	2
DAMPER RUBBER,SIGNAL (Ref # 17)	92075-238	2
CAP,RR SIG LIGHT STAY (Ref # 18)	92102-013	2
COLLAR,RR SIG LIGHT (Ref # 19)	92027-225	2
WASHER PLAIN 12MM (Ref # 20)	411B1200	2
NUT-HEX-FINE,12MM (Ref # 21)	315B1200	2