


1978 KZ400-A2 PARTS DIAGRAM

TURN SIGNALS



1978 KZ400-A2 PARTS LIST

TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
BOLT-UPSET (Ref # 1)	112G0630	
WASHER PLAIN 6MM (Ref # 2)	410B0600	
LAMP-TURN SIGNAL (Ref # 3)	23040-029	
WASHER SPRING 6MM (Ref # 4)	461F0600	
NUT 6MM (Ref # 5)	311B0600	
BKT TURN SIGNL LIGHT (Ref # 6)	23051-049	
CAP,SIGNAL LIGHT STAY (Ref # 7)	92102-015	
COLLAR (Ref # 8)	92027-281	
BRACKET,TURN SIG LAMP (Ref # 9)	23051-054	
DAMPER RUBBER,SIGNAL (Ref # 10)	92075-238	
CAP,FR SIG LIGHT STAY (Ref # 11)	92102-014	
WIRE TURN SIGNAL LEAD (Ref # 12)	26011-081	
NUT-HEX-FINE,12MM (Ref # 13)	315B1200	
DAMPER RUBBER,SIGNAL (Ref # 14)	92075-241	
COLLAR,RR SIG LIGHT (Ref # 15)	92027-225	
CAP,RR SIG LIGHT STAY (Ref # 16)	92102-013	
WASHER PLAIN 12MM (Ref # 17)	411B1200	
BULB 12V 32CP (Ref # 18)	92069-055	
GASKET,TURN SIG LAMP (Ref # 19)	23050-002	
LENS-SIGNAL LAMP (Ref # 20)	23048-1024	
LENS-SIGNAL LAMP (Ref # 20)	23048-1024	
WASHER-PLAIN,4MM (Ref # 21)	23058-002	
SCREW-PAN HEAD,4X35 (Ref # 22)	220E0435A	
WASHER SPRING 12MM (Ref # 23)	461F1200	
BOLT,HEX HEAD,12X45 (Ref # 24)	113B1245A	
NUT 12MM (Ref # 25)	92020-014	