

1974 Mach IV PARTS DIAGRAM

TURN SIGNALS (H2/A)

NO IMAGE AVAILABLE

1974 Mach IV PARTS LIST

TURN SIGNALS (H2/A)

ITEM NAME	PART NUMBER	QUANTITY
LAMP-TURN SIGNAL (Ref # 1)	23040-029	
SCREW-PAN HEAD,4X35 (Ref # 2)	220E0435A	
LENS-SIGNAL LAMP (Ref # 3)	23048-1024	
LENS-SIGNAL LAMP (Ref # 3)	23048-1024	
GASKET,TURN SIG LAMP (Ref # 4)	23050-002	
BULB 12V 32CP (Ref # 5)	92069-055	
WASHER-PLAIN,4MM (Ref # 6)	23058-002	
BRACKET,TURN SIGNAL (Ref # 7)	23051-047	
NUT,12MM (Ref # 8)	314N1200A	
NUT,12MM (Ref # 8)	314N1200A	
WASHER SPRING 12MM (Ref # 9)	461F1200	
BOLT-UPSET (Ref # 10)	112G0630	
WASHER-PLAIN,6MM (Ref # 11)	411D0600	
WASHER SPRING 6MM (Ref # 12)	461F0600	
NUT,6MM (Ref # 13)	311N0600	
BKT-RR SIGNAL LAMP (Ref # 14)	23051-028	
BOLT-HEAX HEAD,10X65 (Ref # 15)	113N1065	
WASHER SPRING 10MM (Ref # 16)	461F1000	
WASHER 22MM (Ref # 17)	92022-106	
COLLAR (Ref # 18)	92027-137	
DAMPER RUBBER,A (Ref # 19)	92075-114	
PLATE-EARTH (Ref # 20)	23061-003	
DAMPER RUBBER,B (Ref # 21)	92075-111	