


1979 KZ1300-A1 PARTS DIAGRAM

CABLES



1979 KZ1300-A1 PARTS LIST

CABLES

| ITEM NAME | PART NUMBER | QUANTITY |
|---------------------------------|-------------|----------|
| GUIDE,TACHOMETER CABL (Ref # 1) | 13070-1012 | 1 |
| GUIDE,CLUTCH CABLE (Ref # 2) | 13070-1013 | 1 |
| GUIDE,SPEEDOMETER (Ref # 3) | 13070-1015 | 1 |
| GUIDE,CLUTCH CABLE (Ref # 4) | 13070-1016 | 1 |
| GUIDE,THROTTLE CABLE (Ref # 5) | 13070-1017 | 1 |
| BOLT-UPSET,6X12 (Ref # 6) | 112G0612 | 3 |
| WASHER SPRING 6MM (Ref # 7) | 461F0600 | 3 |
| BOLT-UPSET,6X12 (Ref # 8) | 112G0612 | 1 |
| WASHER SPRING 6MM (Ref # 9) | 461F0600 | 1 |
| WASHER PLAIN 6MM (Ref # 10) | 411B0600 | 1 |
| CABLE,SPEEDOMETER (Ref # 11) | 54001-1013 | 1 |
| CABLE-CLUTCH (Ref # 12) | 54011-1139 | 1 |
| CABLE,THROTTLE (Ref # 13) | 54012-1027 | 1 |
| CABLE,THROTTLE (Ref # 14) | 54012-1028 | 1 |
| CABLE,TACHOMETER (Ref # 15) | 54018-1005 | 1 |
| CLAMP,CABLE (Ref # 16) | 92037-093 | 2 |