


1982 CSR Belt PARTS DIAGRAM

TURN SIGNALS

F2730-0004



1982 CSR Belt PARTS LIST

TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
GASKET-SIG LAMP LENS (Ref # 11009)	23050-003	4
LAMP,TURN SIGNAL (Ref # 23040)	23040-054	4
LENS,TURN SIGNAL LAMP (Ref # 23048)	23048-1001	4
BRACKET,TURN SIGNAL (Ref # 23051)	23051-1014	2
BRACKET,SIGNAL LAMP (Ref # 23051A)	23051-1024	2
NUT,FLANGED,10MM (Ref # 92015)	92015-1428	4
COLLAR (Ref # 92027)	92027-147	2
BULB 12V 32CP (Ref # 92069)	92069-055	4
WASHER-PLAIN,4MM (Ref # 92075)	23058-002	8
DAMPER RUBBER (Ref # 92075A)	92075-128	2
DAMPER RUBBER,SIG LM (Ref # 92075B)	92075-158	2
BOLT-UPSET (Ref # 110)	112G0630	4
SCREW-PAN HEAD,4X20 (Ref # 220)	220E0420A	8
NUT 6MM (Ref # 311)	311B0600	4
WASHER PLAIN 6MM (Ref # 411)	411B0600	8
WASHER-PLAIN,10MM (Ref # 411A)	411D1000	2
WASHER SPRING 6MM (Ref # 461)	461F0600	4