


1992 KDX200 PARTS DIAGRAM

Meter

F2530



1992 KDX200 PARTS LIST

Meter

ITEM NAME	PART NUMBER	QUANTITY
NUT-HEX (Ref # 311)	311B0500	2
BRACKET,METER (Ref # 11046)	11046-1415	1
WASHER,5.2X16X1.2 (Ref # 92022)	92022-263	2
COLLAR,METER BRACKET (Ref # 92027)	92027-1585	4
DAMPER (Ref # 92075)	92075-013	2
DAMPER (Ref # 92075A)	92075-1841	2
BOLT,6X14 (Ref # 92150)	92150-1340	2
DAMPER (Ref # 92160)	92160-1110	2
SPEEDOMETER,TRIP(MILE) (Ref # 25005)	25005-1496	1
SPEEDOMETER,TRIP(KM) (Ref # 25005A)	25005-1497	1