


1992 Jet Mate PARTS DIAGRAM

Carburetor

(E1611)



1992 Jet Mate PARTS LIST

Carburetor

| ITEM NAME | PART NUMBER | QUANTITY |
|--|-------------|----------|
| GASKET,CHOKE VALVE (Ref # 11009) | 11009-3729 | 1 |
| GASKET,DIAPHRAGM (Ref # 11009A) | 11009-3730 | 1 |
| CAP,JET NEEDLE (Ref # 11012) | 11012-3727 | 2 |
| PLATE (Ref # 13183) | 13183-3707 | 1 |
| COVER,CARBURETOR (Ref # 14024) | 14024-3765 | 1 |
| CARBURETOR-ASSY (Ref # 15001) | 15001-3751 | 1 |
| NEEDLE-JET,HIGH SPEED (Ref # 16009) | 16009-3705 | 1 |
| NEEDLE-JET,LOW SPEED (Ref # 16009A) | 16009-3706 | 1 |
| SCREW-THROTTLE STOP (Ref # 16021) | 16021-3702 | 1 |
| VALVE-FLOAT (Ref # 16030) | 16030-3701 | 1 |
| ARM-FLOAT (Ref # 16055) | 16055-3701 | 1 |
| VALVE-CHECK (Ref # 16087) | 16087-3702 | 1 |
| JET-SLOW,#58 (Ref # 16158) | 16158-3704 | 1 |
| CASE,CARBURETOR (Ref # 32099) | 32099-3744 | 1 |
| DIAPHRAGM,CARBURETOR (Ref # 43028) | 43028-3704 | 1 |
| FILTER-FUEL,STRAINER (Ref # 49019) | 49019-3707 | 1 |
| SCREW,3X6 (Ref # 92009) | 92009-3710 | 2 |
| SCREW,3X6 (Ref # 92009A) | 92009-3712 | 1 |
| SCREW,4X16 (Ref # 92009B) | 92009-3739 | 4 |
| WASHER,ADJUST SCREW (Ref # 92022) | 92022-3745 | 2 |
| PIN,FLOAT (Ref # 92043) | 92043-1209 | 1 |
| PIN,THROTTLE STOP SCREW (Ref # 92043A) | 92043-3712 | 1 |
| RING-O (Ref # 92055) | 92055-1246 | 2 |
| RING-O,ADJUST SCREW (Ref # 92055A) | 92055-3713 | 2 |
| RING-O (Ref # 92055B) | 92055-3720 | 1 |
| JET-MAIN,2ND,#125 (Ref # 92063) | 92063-1069 | 1 |
| COLLAR,THROTTLE STOP SCREW (Ref # 92143) | 92143-3709 | 1 |
| SPRING,ADJUST SCREW (Ref # 92144) | 92144-3704 | 2 |
| SPRING,FLOAT VALVE (Ref # 92144A) | 92144-3705 | 1 |

1992 Jet Mate PARTS LIST

Carburetor

| ITEM NAME | PART NUMBER | QUANTITY |
|---|-------------|----------|
| SPRING,THROTTLE STOP SCREW (Ref # 92144B) | 92144-3706 | 1 |
| SCREW-PAN-CROS (Ref # 220) | 220D0408 | 1 |