


# 1995 X2 PARTS DIAGRAM

Cables



## 1995 X2 PARTS LIST

### Cables

ITEM NAME	PART NUMBER	QUANTITY
BOLT,5X16 (Ref # 110)	110R0516	4
NUT-HEX,5MM (Ref # 311)	311R0500	1
W-PLAIN-S,10MM (Ref # 410)	410S1000	1
O RING,11MM (Ref # 670)	670B2011	4
PLATE (Ref # 13169)	13169-3713	1
ROD,L=40 (Ref # 46102)	46102-3706	1
ROD,5X125 (Ref # 46102A)	46102-3707	1
ROD (Ref # 46102B)	46102-3714	1
BOOT (Ref # 49006)	49006-3706	1
CABLE-THROTTLE (Ref # 54012)	54012-3728	1
CABLE-CHOKE (Ref # 59401)	59401-3709	1
CABLE-STRG,UP&DOWN (Ref # 59406)	59406-3711	1
CABLE-STRG,LEFT&RIGHT (Ref # 59406A)	59406-3721	1
NUT,5MM (Ref # 92015)	92015-3754	1
NUT,20MM (Ref # 92015A)	92015-526	4
WASHER (Ref # 92022)	92022-535	4
RING-SNAP (Ref # 92036)	92036-501	4