


1991 X2 PARTS DIAGRAM

Generator

E1810



1991 X2 PARTS LIST

Generator

ITEM NAME	PART NUMBER	QUANTITY
SCREW-PAN-CROS (Ref # 220)	220B0512	2
SCREW-PAN-WP-CROS (Ref # 235)	235B0616	2
STATOR (Ref # 21003)	21003-3707	1
ROTOR,MAGNETO (Ref # 21007)	21007-3709	1
KEY,WOODRUFF (Ref # 92038)	92038-001	1
BOLT (Ref # 92150)	92150-3806	1