


1982 KZ1300-A4 PARTS DIAGRAM

SWING ARM

F2140-0124



1982 KZ1300-A4 PARTS LIST

SWING ARM

ITEM NAME	PART NUMBER	QUANTITY
COVER,SWING ARM (Ref # 14025)	14025-1087	2
STOPPER,SWING ARM (Ref # 32085)	32085-1053	2
ARM,SWING (Ref # 33001)	33001-1026	1
SHAFT,SWING ARM (Ref # 33032)	33032-1016	2
BOOT,SWING ARM (Ref # 49006)	49006-1020	1
SCREW,14X22 (Ref # 92009)	92009-1087	2
CLAMP,SWING ARM BOOT (Ref # 92037)	92037-1097	2
OIL SEAL,26406 (Ref # 92049)	92049-1030	2
BRG,ROLLER,4T30203E1 (Ref # 92116)	92116-1001	2
SCREW-PAN-CROS (Ref # 220)	220B0420	1
SCREW-PAN-CROS (Ref # 220A)	220B0430	1
NUT 14MM (Ref # 315)	315B1400	2
PIN,SPRING,3X14 (Ref # 555)	555A0314	2