


2001 Ultra 130 PARTS DIAGRAM

Cables

F3175



2001 Ultra 130 PARTS LIST

Cables

ITEM NAME	PART NUMBER	QUANTITY
O RING,11MM (Ref # 670)	670B2011	1
BRACKET (Ref # 11050)	11050-3767	1
BRACKET (Ref # 11051)	11051-3701	1
HOLDER (Ref # 13091)	13091-3712	1
PLATE (Ref # 13183)	13183-3809	1
HOLDER-CABLE (Ref # 14044)	14044-3736	1
CABLE-THROTTLE (Ref # 54012)	54012-3767	1
CABLE-STRG (Ref # 59406)	59406-3771	1
BOLT,6X30 (Ref # 92002)	92002-3726	1
NUT,20MM (Ref # 92015)	92015-526	1
WASHER,6.5X20X1.5 (Ref # 92022)	92022-3710	1
WASHER (Ref # 92022A)	92022-535	1
BUSHING (Ref # 92028)	92028-3769	1
RING-SNAP (Ref # 92036)	92036-501	1
COLLAR,6.2X10X19 (Ref # 92143)	92143-3733	1
BOLT,6X20 (Ref # 92150)	92150-3758	3
BOLT,5X16 (Ref # 92150A)	92150-3778	1
NUT (Ref # 92210)	92210-3746	1