

1981 KZ750-E2 PARTS DIAGRAM

CHASSIS ELECTRICAL EQUIPMENT ('81 -'82 K

NO IMAGE AVAILABLE

1981 KZ750-E2 PARTS LIST

CHASSIS ELECTRICAL EQUIPMENT ('81 -'82 K

| ITEM NAME | PART NUMBER | QUANTITY |
|--------------------------------------|-------------|----------|
| WIRING HARNESS,CENTER (Ref # 26001) | 26001-1117 | 1 |
| HARNESS,MAIN (Ref # 26001A) | 26001-1211 | 1 |
| FUSE ASSY (Ref # 26004) | 26004-1006 | 1 |
| FUSE-ASSY,ACCESSORY (Ref # 26004A) | 26004-1014 | 1 |
| FUSE 10A (Ref # 26006) | 26006-003 | 3 |
| FUSE-20A (Ref # 26006A) | 26006-005 | 2 |
| FUSE,10A,L=30M/M (Ref # 26006B) | 26006-1002 | 3 |
| LEAD WIRE,SIGNAL LAMP (Ref # 26011) | 26011-063 | 3 |
| WIRE-LEAD,ACCESSORY G (Ref # 26011A) | 26011-1100 | 1 |
| WIRE-LEAD,BATTERY (Ref # 26011B) | 26011-1101 | 1 |
| WIRE-LEAD,BATTERY GRO (Ref # 26011C) | 26011-1102 | 1 |
| FB BAT FB12A-A (Ref # 26012) | 26012-1004 | 1 |
| 26012-1210 (Canada) (Ref # 26012A) | 26012-1005 | 1 |
| RELAY-TURN SIGNAL (Ref # 27002) | 27002-011 | 1 |
| RELAY,TURN SIGNAL (Ref # 27002A) | 27002-016 | 1 |
| HORN (Ref # 27003) | 27003-076 | 1 |
| SWITCH,FUEL CHECK (Ref # 27010) | 27010-1015 | 1 |
| SWITCH,RESERVE LIGHTI (Ref # 27010A) | 27010-1024 | 1 |
| LABEL-WARNING,BATTERY (Ref # 56037) | 56040-1036 | 1 |
| BOLT,HEX HEAD,6MM (Ref # 92001) | 92001-137 | 1 |
| CLAMP,WIRING HARNESS (Ref # 92037) | 92037-1069 | 1 |
| BAND,SHORT (Ref # 92072) | 92072-030 | 4 |
| BAND,MIDDLE (Ref # 92072A) | 92072-031 | 1 |
| BAND,WIRING HARNESS (Ref # 92072B) | 92072-056 | 4 |
| DAMPER RUBBER,FUSE (Ref # 92075) | 92075-279 | 1 |
| BOLT-SMALL-UPSET,8X16 (Ref # 114) | 115G0816 | 2 |
| SCREW PAN HEAD 6X20 (Ref # 220) | 220B0620 | 2 |
| WASHER PLAIN 6MM (Ref # 410) | 410B0600 | 2 |
| WASHER SPRING 6MM (Ref # 461) | 461F0600 | 3 |

1981 KZ750-E2 PARTS LIST

CHASSIS ELECTRICAL EQUIPMENT ('81 -'82 K

| ITEM NAME | PART NUMBER | QUANTITY |
|--------------------------------|-------------|----------|
| WASHER SPRING 8MM (Ref # 461A) | 461F0800 | 2 |