


1987 Ninja® 600 PARTS DIAGRAM

SWING ARM

F2141-0824



R	N
1	
3	
3	
3	
4	
5	
9	
9	
9	
9	
9	

1987 Ninja® 600 PARTS LIST

SWING ARM

ITEM NAME	PART NUMBER	QUANTITY
CAP,SWING ARM (Ref # 11012)	11012-1441	2
ARM-COMP-SWING,SILVER (Ref # 33001)	33001-1236-CE	1
SHAFT-SWING ARM (Ref # 33032)	33032-1114	1
ADJUSTER-CHAIN (Ref # 33040)	33040-1063	2
SLEEVE,SWING ARM (Ref # 42036)	42036-1018	1
GUARD,CHAIN (Ref # 55020)	55020-1188	1
BOLT,8X50 (Ref # 92002)	92002-1060	2
NUT,FLANGED,10MM (Ref # 92015)	92015-1428	2
NUT,14MM (Ref # 92015A)	92015-1407	1
BEARING-NEEDLE,TA2230 (Ref # 92046)	92046-1140	2
SEAL-OIL,MHA22304 (Ref # 92049)	92049-1219	2