


# 1981 KDX80 PARTS DIAGRAM

## SWING ARM/SHOCK ABSORBERS



# 1981 KDX80 PARTS LIST

## SWING ARM/SHOCK ABSORBERS

ITEM NAME	PART NUMBER	QUANTITY
CAP,SWING ARM (Ref # 1)	11012-1110	
GUIDE,CHAIN (Ref # 2)	12053-1029	
ARM,SWING,C.SILVER (Ref # 3)	33001-1053	
SLEEVE,SWING ARM (Ref # 4)	42036-1033	
SHIM,22.1X27.6X0.5 (Ref # 5)	92025-1197	
BUSHING,22X28X23.5 (Ref # 6)	92028-1078	
OIL SEAL (Ref # 7)	92049-1053	
SHAFT,SWING ARM PIVOT (Ref # 8)	33032-1007	
NUT (Ref # 9)	92015-1774	
NUT 6MM (Ref # 10)	311B0600	
ADJUSTER,CHAIN (Ref # 11)	33040-1009	
BOLT,6X38 (Ref # 12)	92001-1463	
BOLT 6X35 (Ref # 13)	110R0635	
BOLT-UPSET (Ref # 14)	112G0645	
GUIDE,CHAIN (Ref # 15)	12053-1030	
RETAINER,CHAIN GUIDE (Ref # 16)	14020-1006	
BOLT-UPSET 6X14 (Ref # 17)	112B0614	
NUT 6MM (Ref # 18)	311B0600	
WASHER PLAIN 6MM (Ref # 19)	411B0600	
WASHER SPRING 6MM (Ref # 20)	461F0600	
GUARD,CHAIN,OUTSIDE (Ref # 21)	55020-1017	
GUARD,CHAIN,INSIDE (Ref # 22)	55020-1018	
SPACER,10X13.2X22 (Ref # 23)	92026-1040	
BOLT-FLANGED,6X10 (Ref # 24)	130G0610	
BOLT,FLANGED,10X33 (Ref # 25)	92001-1308	
WASHER,12.3X22X1.6 (Ref # 26)	92022-1065	
WASHER 6.5X22X1.6T (Ref # 27)	92022-237	
SHOCK ABSBR RR (Ref # 28)	45014-1057	
BUSHING, SHCK ABS RUB (Ref # 29)	45017-012	

# 1981 KDX80 PARTS LIST

## SWING ARM/SHOCK ABSORBERS

ITEM NAME	PART NUMBER	QUANTITY
COLLAR,SHOCK ABSORBER (Ref # 30)	92027-1016	
BUSHING,SHOCK ABSORB (Ref # 31)	45016-008	
CAP,SWING ARM (Ref # 32)	11012-1065	
SLEEVE,SWING ARM (Ref # 33)	42036-1022	
BEARING-NEEDLE,HK2216 (Ref # 34)	92046-1115	