


1981 KDX80 PARTS DIAGRAM

CABLES/NUMBER PLATE



1981 KDX80 PARTS LIST

CABLES/NUMBER PLATE

ITEM NAME	PART NUMBER	QUANTITY
SCREW PAN HEAD 5X10 (Ref # 1)	220B0510	
WASHER SPRING 5MM (Ref # 2)	461F0500	
BOLT-UPSET,6X12 (Ref # 3)	112G0612	
WASHER PLAIN 6MM (Ref # 4)	411B0600	
WASHER SPRING 6MM (Ref # 5)	461F0600	
CLAMP,CABLE (Ref # 6)	92037-092	
BOLT-UPSET (Ref # 7)	112G0618	
NUT 6MM (Ref # 8)	311B0600	
WASHER SPRING 6MM (Ref # 9)	461F0600	
CLAMP,CABLE (Ref # 10)	92037-092	
CABLE,BRAKE,FRONT (Ref # 11)	54005-1013	
CABLE,CLUTCH (Ref # 12)	54011-1035	
CABLE,THROTTLE (Ref # 13)	54012-1022	
BAND,WIRING HARNESS (Ref # 14)	92072-056	
PLATE,NUMBER,L.GREEN (Ref # 15)	58029-1002-6W	
"O" RING,135MM (Ref # 16)	92055-1058	