


1976 KH100-B7 PARTS DIAGRAM

CABLES



1976 KH100-B7 PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 1)	54001-014	1
CABLE, FRONT BRAKE (Ref # 2)	54005-033	1
DUST COVER-BRKE CABLE (Ref # 3)	54009-008	1
JOINT-BRAKE ROD (Ref # 4)	92043-082	1
NUT-BRAKE ROD ADJUST (Ref # 5)	92015-052	1
CABLE,CLUTCH (Ref # 6)	54011-075	1
CABLE,CONTROL (Ref # 7)	54012-115	1
CABLE,STARTER (Ref # 8)	54017-067	1
SPRING,COIL (Ref # 9)	54025-004	1
CLAMP-CABLE (Ref # 10)	92037-069	1
CLAMP-CABLE (Ref # 11)	92037-069	2
BAND,SHORT (Ref # 12)	92072-030	1