


1972 Mach II PARTS DIAGRAM

METERS/IGNITION SWITCH (S2-A)

Re



(S2-A)

1972 Mach II PARTS LIST

METERS/IGNITION SWITCH (S2-A)

ITEM NAME	PART NUMBER	QUANTITY
SPEEDOMETER ASSY,MPH (Ref # 1)	25005-124	1
SPEEDOMETER ASSY,MPH (Ref # 1)	25005-124	1
COVER-METER (Ref # 2)	25012-012	2
RING-METER (Ref # 3)	25026-001	2
DAMPER RUBBER-METER (Ref # 4)	25019-015	2
DAMPER RUBBER-METER (Ref # 5)	25019-013	4
WASHER PLAIN 5MM (Ref # 6)	411B0500	4
WASHER SPRING 5MM (Ref # 7)	461F0500	4
NUT,5MM (Ref # 8)	92015-059	4
TACHOMETER ASSY (Ref # 9)	25016-020	1
SOCKET-METER (Ref # 10)	25011-029	1
BULB 12V 1.5W (Ref # 11)	92069-017	1
BULB 12V 3W (Ref # 12)	92069-018	5
COVER-METER CASE (Ref # 13)	25023-002	1
DAMPER RUBBER-METER (Ref # 14)	25019-014	1
HOLDER-METER CASE COV (Ref # 15)	25014-004	2
SCREW PAN HEAD 4X8 (Ref # 16)	220B0408	6
WASHER SPRING 4MM (Ref # 17)	461F0400	6
COVER-METER SOCKET (Ref # 18)	25023-003	1
CASE-METER (Ref # 19)	25008-026	1
HOLDER-METER CASE (Ref # 20)	25014-003	1
SWITCH-ASSY (Ref # 21)	27005-1021	1
SWITCH-ASSY (Ref # 21)	27005-1021	1
NUT-IGNITION SWITCH (Ref # 22)	27007-003	1
WASHER-IGNITION (Ref # 23)	27019-002	1
KEY SET,#181 (Ref # 24)	27008-048-81	AR
KEY SET,#185 (Ref # 24)	27008-048-85	AR
SCREW PAN HEAD 5X8 (Ref # 25)	220B0508	2
WASHER SPRING 5MM (Ref # 26)	461F0500	2