


1981 KDX420 PARTS DIAGRAM

SHOCK ABSORBER



1981 KDX420 PARTS LIST

SHOCK ABSORBER

ITEM NAME	PART NUMBER	QUANTITY
SHOCK ABSBR RR (Ref # 1)	45014-4008	1
GUIDE,SPRING (Ref # 2)	13070-1041	1
SPRING GUIDE,SHK ABS (Ref # 3)	13070-4003	1
WASHER,SPRING (Ref # 4)	92022-1235	1
NUT,SPRING ADJUST (Ref # 5)	92015-1139	1
NUT,SPRING ADJUST (Ref # 6)	92015-1140	1
BUSHING-RUBBER,SHOCKA (Ref # 7)	92092-1008	1
SPRING,RR SHOCK,STD (Ref # 8)	92081-1372	1
SPRING (Ref # 8)	92081-1320	(1
SPRING (Ref # 8)	92081-1322	(1