


# 1982 KZ1000-J2 PARTS DIAGRAM

## CABLES

F2540-0140



# 1982 KZ1000-J2 PARTS LIST

## CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE-CLUTCH (Ref # 54011)	54011-1147	1
CABLE-THROTTLE (Ref # 54012A)	54012-1110	1
CLAMP,CABLE (Ref # 92037)	92037-093	1
CLAMP (Ref # 92037B)	92037-1250	1
CLAMP (Ref # 92037C)	92037-1251	1
CLAMP (Ref # 92037D)	92037-1252	1