


1977 KZ1000 PARTS DIAGRAM

CARBURETOR ASSY ('77-'78 A1/A2/A2A)



1977 KZ1000 PARTS LIST

CARBURETOR ASSY ('77-'78 A1/A2/A2A)

ITEM NAME	PART NUMBER	QUANTITY
CARBURETOR ASSY (Ref # 1)	16001-1024	1
CARBURETOR ASSY (Ref # 1)	16001-1024	1
CARBURETOR ASSY (Ref # 1)	16001-1025	1
CARBURETOR ASSY (Ref # 1)	16001-1023	1
CARB ASSY,L.H OUTSID (Ref # 2)	16001-311	1
CARBURETOR L.H OUT (Ref # 2)	16001-1056	1
CARBURETOR,L.H,OUTSI (Ref # 2)	16001-1075	1
CARB ASSY,L.H INSIDE (Ref # 3)	16001-312	1
CARBURETOR,L.H.INSID (Ref # 3)	16001-1057	1
CARBURETOR,L.H INSID (Ref # 3)	16001-1076	1
CARB ASSY,R.H INSIDE (Ref # 4)	16001-313	1
CARBURETOR,R.H INSID (Ref # 4)	16001-1058	1
CARBURETOR,R.H INSID (Ref # 4)	16001-1077	1
CARB ASSY,R.H OUTSID (Ref # 5)	16001-314	1
CARBURETOR R.H OUT (Ref # 5)	16001-1059	1
CARBURETOR,R.H OUTSI (Ref # 5)	16001-1078	1
SCREW (Ref # 6)	16046-005	1
SPRING,F (Ref # 7)	16040-009	1
WASHER PLAIN 5MM (Ref # 8)	410B0500	1
WASHER,PLAIN (Ref # 9)	16039-019	1
SHAFT,STARTER PLUNGE (Ref # 10)	16041-021	1
SCREW,PAN HEAD,5X7 (Ref # 11)	16046-007	4
LEVER,STARTER PLUNGE (Ref # 12)	13168-1026	4
LEVER,STARTER PLUNGE (Ref # 12)	13168-1026	4
SCREW-PAN-CROS (Ref # 13)	220B0514A	7
SCREW-PAN-CROS (Ref # 13-1)	220B0514A	3
WASHER SPRING 5MM (Ref # 14)	461F0500	8
WASHER SPRING 5MM (Ref # 14-1)	461F0500	4
PLATE,SHAFT STOPPER (Ref # 15)	16055-012	1

1977 KZ1000 PARTS LIST

CARBURETOR ASSY ('77-'78 A1/A2/A2A)

ITEM NAME	PART NUMBER	QUANTITY
SHAFT,CARB CONNECTIO (Ref # 16)	16041-022	1
SHAFT,CARB CONNECTIO (Ref # 16-1)	16041-017	1
SPRING,CABLE PULLY (Ref # 17)	16040-022	1
BRACKET,CABLE PULLY (Ref # 18)	16077-014	1
BRACKET,THROTTLE CAB (Ref # 18-1)	16077-017	1
BOLT,HEX HEAD,5X14 (Ref # 19)	16067-006	1
PULLY,THROTTLE CABLE (Ref # 20)	16068-017	1
PULLEY,THROTTLE CABL (Ref # 20-1)	16068-015	1
RING (Ref # 21)	16073-016	2
CIRCLIP 3MM (Ref # 22)	482K3000	2
HOLDER,THROTTLE SCRE (Ref # 23)	16077-013	1
SCREW,THROTTLE STOP (Ref # 24)	16021-028	1
SCREW,THROTTLE STOP (Ref # 24-1)	16021-033	1
SPRING,THROTTLE STOP (Ref # 25)	16022-017	1
HOLDER,CARB MOUNTING (Ref # 26)	16065-039	1
HOLDER,CARBURETOR (Ref # 26-1)	16065-049	1
SPRING,CABLE PULLY (Ref # 27)	16040-020	1
SPRING,THROTTLE PULL (Ref # 27-1)	92081-1028	1
ADJUSTER,THROTTLE LE (Ref # 28)	16021-020	1
SCREW (Ref # 28-1)	16021-032	1
SPRING,THROTTLE ADJS (Ref # 29)	16022-010	1
BRK,THROT CABLE PULL (Ref # 30)	16077-018	1
BRACKET,THROTTLE CAB (Ref # 30-1)	16077-016	1
JOINT,FUEL PIPE (Ref # 31)	16046-002	2
CLAMP,CARB CONECT HO (Ref # 32)	92037-056	4
HOSE,FUEL (Ref # 33)	92059-144	1
SCREW,6X14 (Ref # 34)	16033-029	8
CAP,RUBBER (Ref # 35)	16039-042	2
GROMMET,CARBURETOR (Ref # 36)	92071-104	6

1977 KZ1000 PARTS LIST

CARBURETOR ASSY ('77-'78 A1/A2/A2A)

ITEM NAME	PART NUMBER	QUANTITY
HOSE,6X11.5X16 (Ref # 37)	92059-141	2
HOSE,AIR VENT,5X8X55 (Ref # 38)	92059-1028	1
HOSE,AIR VENT,5X8X55 (Ref # 38)	92059-1028	1
HOSE,AIR VENT,5X8X55 (Ref # 39)	92059-1028	1
HOSE,AIR VENT,5X8X55 (Ref # 39)	92059-1028	1
HOSE,FUEL OVERFLOW (Ref # 40)	92059-147	4
CLAMP,OVERFLOW HOSE (Ref # 41)	92037-173	4
PLATE,CARB CONNECTIO (Ref # 42)	16065-040	1
SCREW CNTSNK HD 5X10 (Ref # 43)	221B0510A	2
HOSE,FUEL TAP DIAPHR (Ref # 44)	92059-1023	1
CLAMP-PIPE (Ref # 45)	92037-072	2
HOSE,6.50X11.50X100 (Ref # 46)	92059-1059	1