


1978 KZ1000 PARTS DIAGRAM

CARBURETOR PARTS ('77-'78 A1/A2/A2A)



1978 KZ1000 PARTS LIST

CARBURETOR PARTS ('77-'78 A1/A2/A2A)

| ITEM NAME | PART NUMBER | QUANTITY |
|--------------------------------|-------------|----------|
| SCREW PAN HEAD 4X16 (Ref # 40) | 220B0416A | 6 |