

1979 KZ1000 PARTS DIAGRAM

CHASSIS ELECTRICAL EQUIPMENT ('79-'80 A3)

NO IMAGE AVAILABLE

1979 KZ1000 PARTS LIST

CHASSIS ELECTRICAL EQUIPMENT ('79-'80 A3)

ITEM NAME	PART NUMBER	QUANTITY
FUSE ASSY (Ref # 1)	26004-1006	1
DAMPER RUBBER,FUSE (Ref # 2)	92075-279	1
FUSE-20A (Ref # 3)	26006-005	2
FUSE 10A (Ref # 4)	26006-003	3
WIRING HARNESS,MAIN (Ref # 5)	26001-1054	1
WIRE,STARTER LEAD (Ref # 6)	26011-1047	1
WIRE,LEAD (Ref # 7)	26011-095	2
WIRE,BATTERY GROUND (Ref # 8)	26010-054	1
BOLT,HEX HEAD,6MM (Ref # 9)	92001-137	1
WASHER SPRING 6MM (Ref # 10)	461F0600	1
BAND,SHORT (Ref # 11)	92072-030	1
BAND,WIRING HARNESS (Ref # 12)	92072-056	8
RELAY-TURN SIGNAL (Ref # 13)	27002-011	1
RELAY,TURN SIGNAL (Ref # 14)	27002-016	1
HORN (Ref # 15)	27003-1006	1
BOLT-SMALL-UPSET,8X1 (Ref # 16)	115G0816	1
WASHER SPRING 8MM (Ref # 17)	461F0800	1
CASE,BATTERY (Ref # 18)	32099-015	1
YUA BAT YB14L-A2 (Ref # 19)	26012-1008	1
LABEL-WARNING,BATTER (Ref # 20)	56040-1036	1
CLAMP,WIRING HARNESS (Ref # 21)	92037-1069	1
CAP,FRONT BRK SWITCH (Ref # 22)	11012-1037	1