

# 1979 Shaft PARTS DIAGRAM

TURN SIGNALS

NO IMAGE AVAILABLE

## 1979 Shaft PARTS LIST

### TURN SIGNALS

| ITEM NAME                        | PART NUMBER | QUANTITY |
|----------------------------------|-------------|----------|
| LAMP ASSY,TURN SIGNAL (Ref # 1)  | 23040-1017  | 2        |
| SCREW-PAN-CROS (Ref # 2)         | 220E0412    | 8        |
| WASHER-PLAIN,4MM (Ref # 3)       | 23058-002   | 8        |
| LENS-SIGNAL LAMP (Ref # 4)       | 23048-1022  | 4        |
| GASKET,TURN SIGNAL (Ref # 5)     | 11009-1052  | 4        |
| BULB,12V 23/8W (Ref # 6)         | 92069-060   | 2        |
| BRK,TURN SIGNAL LAMP (Ref # 7)   | 23051-1031  | 2        |
| BOLT-UPSET (Ref # 8)             | 112G0630    | 4        |
| WASHER PLAIN 6MM (Ref # 9)       | 411B0600    | 8        |
| WASHER SPRING 6MM (Ref # 10)     | 461F0600    | 4        |
| NUT 6MM (Ref # 11)               | 311B0600    | 4        |
| DAMPER RUBBER (Ref # 12)         | 92075-128   | 4        |
| NUT 10MM (Ref # 13)              | 315B1000    | 4        |
| LAMP ASSY,TURN SIGNAL (Ref # 14) | 23040-1018  | 2        |
| BULB 12V 32CP (Ref # 15)         | 92069-055   | 2        |
| DAMPER RUBBER,SIG LM (Ref # 16)  | 92075-158   | 4        |
| COLLAR (Ref # 17)                | 92027-147   | 4        |
| WASHER SPRING 10MM (Ref # 18)    | 461F1000    | 4        |
| BRACKET,TURN SIGNAL (Ref # 19)   | 23051-1014  | 2        |