



1981 GPz PARTS DIAGRAM

CABLES

F2540-0042



1981 GPz PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 54001)	54001-1012	1
CABLE-CLUTCH (Ref # 54011)	54011-1025	1
CABLE-THROTTLE,OPEN (Ref # 54012)	54012-1041	1
CABLE-THROTTLE,CLOS (Ref # 54012A)	54012-1042	1
CABLE,TACHOMETER (Ref # 54018)	54018-1008	1
CLAMP,CLUTCH CABLE (Ref # 92037)	92037-1086	1
CLAMP,CLUTCH CABLE (Ref # 92037A)	92037-1170	1
BOLT-UPSET 6X14 (Ref # 110)	112B0614	1
WASHER PLAIN 6MM (Ref # 411)	411B0600	1
WASHER SPRING 6MM (Ref # 461)	461F0600	1