


# 1981 CSR PARTS DIAGRAM

## CABLES

F2540-0050



# 1981 CSR PARTS LIST

## CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 54001)	54001-1029	1
CABLE-CLUTCH (Ref # 54011)	54011-1059	1
CABLE-THROTTLE (Ref # 54012)	54012-1110	1
CABLE,TACHOMETER (Ref # 54018)	54018-015	1
CLAMP,CABLE (Ref # 92037)	92037-093	1
CLAMP,THROTTLE CABLE (Ref # 92037A)	92037-1189	1
CLAMP (Ref # 92037B)	92037-1252	1