


1969 Mach III PARTS DIAGRAM

IGNITION/GENERATOR/REGULATOR (H1/A/C)



(H1/A)

1969 Mach III PARTS LIST

IGNITION/GENERATOR/REGULATOR (H1/A/C)

ITEM NAME	PART NUMBER	QUANTITY
ROTOR S.G (Ref # 1)	21007-011	1
ROTOR (Ref # 2)	21007-012	1
YOKE ASSY (Ref # 3)	21076-007	1
WASHER SPRING 4MM (Ref # 4)	461F0400	12
BRUSH CARBON (Ref # 5)	21088-009	1
PLATE-YOKE (Ref # 6)	21155-001	1
SCREW (Ref # 7)	220R0455	3
WASHER SPRING 5MM (Ref # 8)	461F0500	3
WASHER PLAIN 5MM (Ref # 9)	411B0500	3
SCREW PAN HEAD 4X8 (Ref # 10)	21085-004	8
SCREW PAN HEAD 4X8 (Ref # 10)	220B0408	8
POINTER-IGN TIMING (Ref # 11)	21020-020	1
WASHER PLAIN 4MM (Ref # 12)	410B0400	4
SCREW PAN HEAD 4X25 (Ref # 13)	220B0425	1
SCREW PAN HEAD 4X6 (Ref # 14)	220B0406	1
PLATE-PICK UP (Ref # 15)	21156-001	1
SCREW-PAN-CROS (Ref # 16)	220B0310	2
WASHER SPRING 3MM (Ref # 17)	461F0300	2
PICK UP (Ref # 18)	21152-002	1
CLAMP-LEAD WIRE (Ref # 19)	21098-007	2
WIRING HARNESS (Ref # 20)	21029-009	1
BOLT HEX HEAD 8X73 (Ref # 21)	110B0873	1
WASHER SPRING 8MM (Ref # 22)	461F0800	1
WASHER PLAIN 8MM (Ref # 23)	411B0800	1
ONCORD ASY-HIGH TENSI (Ref # 24)	21150-003	1
COIL IGNITION (Ref # 25)	21121-032	1
BAND IGNITION COIL (Ref # 26)	21126-003	1
BOLT 6X35 (Ref # 27)	110R0635	2
WASHER SPRING 6MM (Ref # 28)	461F0600	14

1969 Mach III PARTS LIST

IGNITION/GENERATOR/REGULATOR (H1/A/C)

ITEM NAME	PART NUMBER	QUANTITY
NUT 6MM (Ref # 29)	311B0600	4
PROTECTOR-CORD (Ref # 30)	92115-002	2
SPRING-SPARK PLUG CAP (Ref # 31)	92101-001	3
CAP SPARK PLUG (Ref # 32)	21130-009	3
IGNITION UNIT A (Ref # 33)	21119-006	1
IGNITION UNIT B (Ref # 34)	21120-004	1
REGULATOR VOLTAGE (Ref # 35)	21072-004	1
RECTIFIER (Ref # 36)	21061-008	1
BOLT-UPSET (Ref # 37)	112G0618	6
BOLT-UPSET,6X12 (Ref # 38)	112G0612	4
WASHER PLAIN 6MM (Ref # 39)	411B0600	2
PROTECTOR CORD (Ref # 40)	92114-002	1