


1984 KE100 PARTS DIAGRAM

CABLES



1984 KE100 PARTS LIST

CABLES

| ITEM NAME | PART NUMBER | QUANTITY |
|-------------------------------------|-------------|----------|
| DUST COVER-BRKE CABLE (Ref # 49016) | 54009-008 | 1 |
| CABLE,SPEEDOMETER (Ref # 54001) | 54001-032 | 1 |
| CABLE-BRAKE (Ref # 54005) | 54005-1035 | 1 |
| CABLE-CLUTCH (Ref # 54011) | 54011-1054 | 1 |
| CABLE-THROTTLE (Ref # 54012) | 54012-1104 | 1 |
| SCREW-PAN-WS-CROS (Ref # 92009) | 223B0510 | 1 |
| NUT-BRAKE ROD ADJUST (Ref # 92015) | 92015-052 | 1 |
| CLAMP-CABLE (Ref # 92037) | 92037-069 | 1 |
| CLAMP-CABLE (Ref # 92037A) | 92037-046 | 1 |
| JOINT-BRAKE ROD (Ref # 92043) | 92043-082 | 1 |
| SPRING,COIL (Ref # 92081) | 54025-004 | 1 |
| BOLT 6X12 (WP) (Ref # 186) | 186B0612 | 1 |