


2003 900 STX PARTS DIAGRAM

Cables



2003 900 STX PARTS LIST

Cables

ITEM NAME	PART NUMBER	QUANTITY
BOLT-WS,6X18 (Ref # 150)	150R0618	2
WASHER-PLAIN,8MM (Ref # 411)	411S0800	1
O RING,8MM (Ref # 670)	670B1508	1
O RING,11MM (Ref # 670A)	670B2011	2
BRACKET,STARTER CABLE (Ref # 11051)	11051-3744	1
PLATE (Ref # 13183)	13183-3810	1
HOLDER-CABLE,STEERING (Ref # 14044)	14044-3714	2
HOLDER-CABLE,STEERING (Ref # 14044A)	14044-3717	1
HOLDER-CABLE,STEERING (Ref # 14044B)	14044-3731	1
CABLE-THROTTLE (Ref # 54012)	54012-3756	1
REEL (Ref # 59101)	59101-3715	1
CABLE-CHOKE (Ref # 59401)	59401-3726	1
CABLE-STRG,REVERSE (Ref # 59406)	59406-3749	1
CABLE-STRG (Ref # 59406A)	59406-3778	1
BOLT,6X16 (Ref # 92002)	92002-3728	2
BOLT,6X20 (Ref # 92002A)	92002-3755	2
SCREW,5X16 (Ref # 92009)	92009-3789	2
SCREW,4X12 (Ref # 92009A)	92009-3838	1
NUT,20MM (Ref # 92015)	92015-526	2
WASHER,6.5X20X1.5 (Ref # 92022)	92022-3710	2
WASHER (Ref # 92022A)	92022-535	2
RING-SNAP (Ref # 92036)	92036-501	2
PIN (Ref # 92043)	92043-3752	1
PLUG,FUEL&CHOKE KNOB,F.BLACK (Ref # 92066)	92066-3770-6Z	1
GROMMET,HARNESS (Ref # 92071)	92071-3790	1
KNOB,FUEL&CHOKE,F.BLACK (Ref # 92077)	92077-3732-6Z	1
SPRING (Ref # 92145)	92145-3712	1
WASHER,8.5X34X0.5 (Ref # 92200)	92200-3770	1