


1987 KE100 PARTS DIAGRAM

Cable



1987 KE100 PARTS LIST

Cable

ITEM NAME	PART NUMBER	QUANTITY
COVER-SEAL (Ref # 49016)	54009-008	1
CABLE-SPEEDOMETER (Ref # 54001)	54001-032	1
CABLE-BRAKE (Ref # 54005)	54005-1035	1
CABLE-CLUTCH (Ref # 54011)	54011-1054	1
CABLE-THROTTLE (Ref # 54012)	54012-1104	1
BOLT,6X12 (Ref # 92002)	92002-1211	1
NUT,CABLE ADJUSTER LOCK (Ref # 92015)	92015-052	1
CLAMP,CABLE (Ref # 92037)	92037-017	1
CLAMP,CABLE (Ref # 92037A)	92037-046	1
PIN,BRAKE CABLE (Ref # 92043)	92043-082	1
SPRING,CABLE (Ref # 92081)	54025-004	1
SCREW-PAN-WS-CROS (Ref # 223)	223C0510	1