


1999 KE100 PARTS DIAGRAM

Air Cleaner

E1130



1999 KE100 PARTS LIST

Air Cleaner

ITEM NAME	PART NUMBER	QUANTITY
BOLT-UPSET-WSP (Ref # 187)	187C0612	1
SCREW-PAN-CROS,6X8 (Ref # 220)	220B0608	2
WASHER-PLAIN-SMALL,6MM (Ref # 410)	410B0600	2
FILTER-ASSY-AIR (Ref # 11010)	11010-1100	1
CAP,AIR FILTER,F.BLACK (Ref # 11012)	11012-1187	1
ELEMENT-AIR FILTER (Ref # 11013)	11013-1008	1
CLAMP (Ref # 92037)	92037-068	1