


2003 KLX400SR PARTS DIAGRAM

Meter(s)

F2530



2003 KLX400SR PARTS LIST

Meter(s)

ITEM NAME	PART NUMBER	QUANTITY
BRACKET (Ref # 11053)	11053-S030	1
GUIDE,METER CABLE (Ref # 13070)	13070-S020	1
GUIDE,METER CABLE (Ref # 13070A)	13070-S021	1
GUIDE,SPEEDOMETER CABLE (Ref # 13070B)	13070-S022	1
LAMP-ASSY (Ref # 23016)	23016-S005	1
SPEEDOMETER,MPH (Ref # 25005)	25005-S004	1
CABLE-SPEEDMETER (Ref # 54001)	54001-S002	1
BOLT (Ref # 92153)	92153-S012	2
BOLT,6X20 (Ref # 92153A)	92153-S049	1
DAMPER (Ref # 92161)	92161-S117	3
SCREW (Ref # 92172)	92172-S055	1
SCREW (Ref # 92172A)	92172-S132	1
SCREW,PILOT BOX (Ref # 92172B)	92172-S200	2
WASHER,6.5X18X1.6 (Ref # 92200)	92200-S007	1
WASHER (Ref # 92200A)	92200-S190	1
NUT (Ref # 92210)	92210-S001	1
NUT (Ref # 92210A)	92210-S067	1