


1998 Prairie 400 4X4 PARTS DIAGRAM

Drive Converter

E1391



1998 Prairie 400 4X4 PARTS LIST

Drive Converter

ITEM NAME	PART NUMBER	QUANTITY
BALANCER,T=0.8 (Ref # 13041)	13041-1084	AR
BALANCER,T=1.0 (Ref # 13041A)	13041-1085	AR
GUIDE,NONE (Ref # 13070)	13070-1302	AR
GUIDE,1 LINE (Ref # 13070A)	13070-1316	AR
GUIDE,3 LINES (Ref # 13070B)	13070-1317	AR
GUIDE,2 LINES (Ref # 13070C)	13070-1318	AR
COVER-ASSY (Ref # 16146)	16146-1088	1
WEIGHT-RAMP (Ref # 39152)	39152-1053	3
WEIGHT-RAMP (Ref # 39152A)	39152-1060	3
COUPLING-ASSY (Ref # 42033)	42033-1187	1
SLEEVE (Ref # 42036)	42036-1334	1
SHOE (Ref # 49048)	49048-1057	3
SPIDER (Ref # 49050)	49050-1062	1
RAMP,DRIVEN CONVERTER (Ref # 49092)	49092-1058	1
CONVERTER-ASSY-DRIVE (Ref # 49093)	49093-1057	1
CONVERTER-ASSY-DRIVEN (Ref # 49094)	49094-1055	1
SHEAVE-MOVABLE (Ref # 59301)	59301-1058	1
SHEAVE-COMP,FIXED (Ref # 59302)	59302-1064	1
SHEAVE-COMP,MOVABLE (Ref # 59302A)	59302-1065	1
SHEAVE-COMP (Ref # 59302B)	59302-1066	1
NUT,LOCK,6MM (Ref # 92019)	92019-008	3
WASHER (Ref # 92022)	92022-1899	6
WASHER,SPECIAL CONICAL (Ref # 92022A)	92022-1901	3
WASHER,12.5X32X3.2 (Ref # 92022B)	92022-1982	1
SPACER,10X16X0.8 (Ref # 92026)	92026-1304	12
SPACER,32.3X46X1.0 (Ref # 92026A)	92026-1485	AR
SPACER,32.3X46X1.6 (Ref # 92026B)	92026-1486	AR
SPACER (Ref # 92026C)	92026-1491	24
SPACER,32.3X46X1.2 (Ref # 92026D)	92026-1492	AR

1998 Prairie 400 4X4 PARTS LIST

Drive Converter

ITEM NAME	PART NUMBER	QUANTITY
SPACER,32.3X46X0.8 (Ref # 92026E)	92026-1494	AR
SPACER,32.3X46X0.6 (Ref # 92026F)	92026-1495	AR
SPACER,48.7X57.5X1.0 (Ref # 92026G)	92026-1498	AR
BUSHING,43X47X20 (Ref # 92028)	92028-1508	1
BUSHING,40X44X12 (Ref # 92028A)	92028-1511	1
BUSHING,32X36X20 (Ref # 92028B)	92028-1513	1
BUSHING,25X28X30 (Ref # 92028C)	92028-1514	1
PIN,6.5X10X38 (Ref # 92043)	92043-1370	6
ROLLER (Ref # 92122)	92122-1152	3
BOLT-UPSET (Ref # 112)	112G0630	3
SPRING,DRIVEN CONVERTER (Ref # 92144)	92144-1977	1
SPRING,DRIVE CONVERTER (Ref # 92144A)	92144-1978	1
BOLT,6X20 (Ref # 92150)	92150-1014	24
BOLT,CONVERTER,DRIVE (Ref # 92151)	92151-1119	1
BOLT,CONVERTER,DRIVE (Ref # 92151A)	92151-1120	1
WASHER (Ref # 92200)	92200-1295	2
WASHER (Ref # 92200A)	92200-1342	2