


# 1999 Prairie 400 PARTS DIAGRAM

Transmission

E1361



# 1999 Prairie 400 PARTS LIST

## Transmission

ITEM NAME	PART NUMBER	QUANTITY
SHAFT,INPUT (Ref # 13107)	13107-1395	1
SHAFT,OUTPUT (Ref # 13107A)	13107-1396	1
GEAR,OUTPUT,44T (Ref # 13260)	13260-1736	1
SPROCKET-DRIVE,REVERSE,19T (Ref # 39134)	39134-1060	1
WASHER,28.1X34X1.0 (Ref # 92022)	92022-1731	2
RING-SNAP,25.9X30.6X1.2 (Ref # 92033)	92033-1037	2
CHAIN,REVERSE,81RH2520-52 (Ref # 92057)	92057-1465	1