


1995 KX100 PARTS DIAGRAM

Transmission

E1361



1995 KX100 PARTS LIST

Transmission

ITEM NAME	PART NUMBER	QUANTITY
SHAFT-TRANSMISSION INPUT,13T (Ref # 13127)	13127-1217	1
SHAFT-TRANSMISSION OUTPUT (Ref # 13128)	13128-1126	1
GEAR,INPUT 3RD&4TH,18T&20T (Ref # 13129)	13129-1722	1
GEAR,OUTPUT LOW,33T (Ref # 13129A)	13129-1725	1
GEAR,OUTPUT 2ND,30T (Ref # 13129B)	13129-1726	1
GEAR,OUTPUT 5TH,24T (Ref # 13129C)	13129-1729	1
GEAR,OUTPUT 6TH,22T (Ref # 13129D)	13129-1730	1
SPROCKET-OUTPUT,14T (Ref # 13144)	13144-1022	1
SPROCKET-OUTPUT,13T (Ref # 13144A)	13144-1023	1
GEAR,INPUT 2ND,16T (Ref # 13260)	13260-1014	1
GEAR,INPUT 6TH,23T (Ref # 13260A)	13260-1015	1
GEAR,INPUT 5TH,22T (Ref # 13260B)	13260-1022	1
GEAR,OUTPUT 3RD,27T (Ref # 13260C)	13260-1023	1
GEAR,OUTPUT 4TH,25T (Ref # 13260D)	13260-1024	1
COLLAR,20X25X12.5 (Ref # 92027)	92027-1077	1
RING-SNAP (Ref # 92033)	92033-028	2
RING-SNAP,18MM (Ref # 92033A)	92033-1079	4
RING-O,17.5X1.5 (Ref # 92055)	92055-022	1