


1999 KX100 PARTS DIAGRAM

Cables

F2540



1999 KX100 PARTS LIST

Cables

| ITEM NAME | PART NUMBER | QUANTITY |
|------------------------------|-------------|----------|
| CABLE-CLUTCH (Ref # 54011) | 54011-1375 | 1 |
| CABLE-THROTTLE (Ref # 54012) | 54012-1565 | 1 |
| CLAMP (Ref # 92037) | 92037-1608 | 1 |