


# 2005 KX100 PARTS DIAGRAM

Generator

E1810



## 2005 KX100 PARTS LIST

### Generator

ITEM NAME	PART NUMBER	QUANTITY
SCREW-PAN-WP-CROS (Ref # 224)	224B0614	2
STATOR (Ref # 21003)	21003-1366	1
ROTOR,MAGNETO (Ref # 21007)	21007-1239	1
IGNITER (Ref # 21119)	21119-1589	1
NUT,FLANGED,10MM (Ref # 92015)	92015-077	1
CLAMP,L=60 (Ref # 92037)	92037-1069	1
KEY,WOODRUFF (Ref # 92038)	92038-001	1
BOLT,FLANGED,6X16 (Ref # 92150)	92150-1506	2