


# 1990 KX250 PARTS DIAGRAM

Step

F2160



# 1990 KX250 PARTS LIST

## Step

ITEM NAME	PART NUMBER	QUANTITY
STEP,LH (Ref # 34028)	34028-1318	1
STEP,RH (Ref # 34028A)	34028-1319	1
PIN,10X45.5 (Ref # 92043)	92043-1372	2
SPRING,STEP,LH (Ref # 92144)	92144-1511	1
SPRING,STEP,RH (Ref # 92144A)	92144-1512	1
PIN-COTTER,3.0X20 (Ref # 550)	550D3020	2