


2004 KX85 PARTS DIAGRAM

Swingarm

F2141



2004 KX85 PARTS LIST

Swingarm

| ITEM NAME | PART NUMBER | QUANTITY |
|-------------------------------------|---------------|----------|
| BOLT-FLANGED-SMALL (Ref # 132) | 132G0650 | 2 |
| SCREW-PAN-CROS,5X8 (Ref # 220) | 220B0508 | 4 |
| SCREW-CSK-CROS,6X45 (Ref # 221) | 221B0645 | 2 |
| CAP (Ref # 11012) | 11012-1263 | 4 |
| GUIDE-CHAIN,RR,LH (Ref # 12053) | 12053-1203 | 1 |
| GUIDE-CHAIN,RR,RH (Ref # 12053A) | 12053-1204 | 1 |
| GUIDE-CHAIN,FR (Ref # 12053B) | 12053-1414 | 1 |
| PLATE,GUIDE CHAIN (Ref # 13270) | 13270-1829 | 1 |
| PLATE (Ref # 13270A) | 13270-1899 | 2 |
| ARM-COMP-SWING,SILVER (Ref # 33001) | 33001-1542-CE | 1 |
| SHAFT-SWING ARM (Ref # 33032) | 33032-1161 | 1 |
| ADJUSTER-CHAIN (Ref # 33040) | 33040-1173 | 2 |
| SLEEVE,SWING ARM,L=34 (Ref # 42036) | 42036-1067 | 2 |
| BOLT,8X46 (Ref # 92001) | 92001-1179 | 2 |
| SCREW,5X10 (Ref # 92009) | 92009-1828 | 4 |
| NUT,FLANGED,8MM (Ref # 92015) | 92015-1014 | 2 |
| BEARING-NEEDLE (Ref # 92046) | 92046-1046 | 2 |
| COLLAR (Ref # 92143) | 92143-1676 | 4 |
| NUT,LOCK,12MM (Ref # 92210) | 92210-1249 | 1 |