


2003 Z1000 PARTS DIAGRAM

Turn Signals



2003 Z1000 PARTS LIST

Turn Signals

ITEM NAME	PART NUMBER	QUANTITY
GASKET,SIGNAL LAMP (Ref # 11009)	11009-1402	4
LAMP-SIGNAL,RR (Ref # 23040A)	23040-1295	1
LAMP-SIGNAL,RR,RH (Ref # 23040B)	23040-1320	1
LAMP-SIGNAL,FR (Ref # 23040C)	23040-1322	2
LENS-SIGNAL LAMP (Ref # 23048)	23048-1054	2
LENS-SIGNAL LAMP (Ref # 23048A)	23048-1055	2
BRACKET-SIGNAL LAMP (Ref # 23051)	23051-1248	2
BRACKET-SIGNAL LAMP (Ref # 23051A)	23051-1252	2
SCREW,TAPPING,3X16 (Ref # 92009)	92009-1115	8
SCREW,TAPPING,4X20 (Ref # 92009A)	92009-1304	4
NUT,FLANGED,6MM,BLACK (Ref # 92015)	92015-1233	2
NUT,FLANGED,6MM (Ref # 92015A)	92015-1367	2
WASHER,SIGNAL LAMP (Ref # 92022)	92022-1672	4
BULB,12V 21W (Ref # 92069)		2
BULB,12V 21/5W (Ref # 92069A)	92069-1084	2
DAMPER,SIGNAL LAMP (Ref # 92075)	92075-1698	4