


1999 ZRX1100 PARTS DIAGRAM

Transmission

E 1361



1999 ZRX1100 PARTS LIST

Transmission

ITEM NAME	PART NUMBER	QUANTITY
CIRCLIP-TYPE-C,28MM (Ref # 480)	480J2800	2
CIRCLIP (Ref # 480A)	480J2900	1
BALL-STEEL,5/32" (Ref # 600)	600A0500	3
SHAFT-TRANSMISSION INPUT,15T (Ref # 13127)	13127-1257	1
SHAFT-TRANSMISSION OUTPUT (Ref # 13128)	13128-1218	1
SHIFTER (Ref # 13139)	13139-1079	1
SPROCKET-OUTPUT,17T (Ref # 13144)	13144-1283	1
GEAR,INPUT TOP,28T (Ref # 13260)	13260-1500	1
GEAR,INPUT 2ND,19T (Ref # 13260A)	13260-1663	1
GEAR,INPUT 3RD&4TH,23T&26T (Ref # 13260B)	13260-1664	1
GEAR,OUTPUT LOW,41T (Ref # 13260C)	13260-1665	1
GEAR,OUTPUT 2ND,37T (Ref # 13260D)	13260-1666	1
GEAR,OUTPUT 3RD,34T (Ref # 13260E)	13260-1667	1
GEAR,OUTPUT 4TH,31T (Ref # 13260F)	13260-1668	1
GEAR,OUTPUT TOP,29T (Ref # 13260G)	13260-1669	1
NUT,20MM (Ref # 92015)	92015-1210	1
WASHER,28.3X42X2.9 (Ref # 92022)	92022-1219	1
WASHER,22.3X35X1.6 (Ref # 92022A)	92022-212	2
BUSHING,OUTPUT,3RD&4TH (Ref # 92028)	92028-1753	1
BUSHING,INPUT,TOP GEAR (Ref # 92028A)	92028-1802	1
RING-SNAP,20X25.5X1.2 (Ref # 92033)	92033-025	2
BEARING-BALL (Ref # 92045)	92045-1186	2
BEARING-NEEDLE,FWF-223014 (Ref # 92046)	92046-031	2
RACE,INPUT SHAFT (Ref # 92048)	92048-1052	1
RACE,30X38X15 (Ref # 92048A)	92048-1053	1
COLLAR,28X40X33.5 (Ref # 92143)	92143-1731	1
WASHER,TOOTHED,23.9X45X1.0 (Ref # 92200)	92200-1234	1
WASHER,TOOTHED,28X30X2 (Ref # 92200A)	92200-1277	1
WASHER,29.9X40X1.5 (Ref # 92200B)	92200-1278	1

1999 ZRX1100 PARTS LIST

Transmission

ITEM NAME	PART NUMBER	QUANTITY
WASHER (Ref # 92200C)	92200-1340	1