


Mule 500 PARTS DIAGRAM

Driven Converter

E1392



Mule 500 PARTS LIST

Driven Converter

ITEM NAME	PART NUMBER	QUANTITY
SHOE (Ref # 49048)	49048-1055	3
RAMP (Ref # 49092A)	49092-1055	1
CONVERTER-ASSY-DRIVEN (Ref # 49094A)	49094-1054	1
SHEAVE-MOVABLE (Ref # 59301)	59301-1054	1
SHEAVE-COMP (Ref # 59302A)	59302-1062	1
NUT (Ref # 92015A)	92015-1981	1
BUSHING (Ref # 92028)	92028-1651	1
SPRING (Ref # 92144)	92144-1553	1
BOLT (Ref # 92150)	92150-1444	3